

## Walk Audit #1 From Village Green to Glasco via Rock City Road - 7/23/2023

**Whose using the street** ?– all categories of users, all categories of uses except public transit and schoolchildren

**Street Safety and Appeal** – Mixed reviews

Acceptable : places to sit, shade trees, trash receptacles, landscaping, informative signage, public restroom

Questionable or non-existent: shelter from weather, drinking fountains, transit shelter, visible posted speed limit, pedestrian safety from moving vehicles

**Sidewalks, Streets, and Crossings** – Mixed reviews

Acceptable: visible stop signs and crosswalks, surfacing good in places

Questionable or problematic: unclear, poorly painted, and questionably placed crosswalks, curb ends at Community Center, poor signage alerting to pedestrians, surfacing inconsistent and frequently cracked, sidewalk is not continuous, no pedestrian crossing signals

**Public Transit Access** - Mixed reviews

Acceptable: stop is in a useful location, has some seating

Questionable: access not safe (no crosswalk), no amenities, no shelter

**Build a Better Block**

Renovate and repair sidewalks, install raised crosswalks, install artistic crosswalks, add pedestrian bulb-outs, add more outdoor seating, more shade trees, provide some shelters, maintain restrooms better, speed calming, improve litter removal, trim bushes affecting visibility

**Some specific issues:**

- No posted speed on Rock City towards Glasco
- Crosswalks by GoodNight restaurant poorly placed
- Cars do not stop for pedestrians in crosswalks
- Road particularly unsafe from Community Center to Glasco Turnpike
- Sidewalks do not accommodate persons with disabilities
- Inadequate crosswalks and configuration
- No designated bike lane