


Town of Woodstock  
Natural Resources Inventory

## 7. Soils



- State/US Highway
- Local Street
- River/Stream
- Open Water

### Soil Erosion Hazard Rating

- Very severe
- Severe
- Moderate
- Slight
- Not rated

Definition: The hazard of soil loss from off-road and off-trail areas, where 50 to 75 percent of the surface has been exposed by logging, grazing, mining, or other kinds of disturbance.

Data Sources: Roadways: ESRI North American Detailed Streets (2019). | Towns: Ulster County (2018). | Rivers/ Streams/ Waterbodies: Ulster County (2015). | Soils: USDA Soil Conservation Service (2018).

Note: This map is intended for general planning and education purposes and is not a substitute for site-level surveys. The Town of Woodstock Natural Resources Inventory was created with technical assistance from Cornell University, the NYS DEC Hudson River Estuary Program, Ulster County, and the Ashokan Watershed Stream Management Program. Map created December 1, 2020.

